

GCW Great Lakes East Division Mileages

Eastward
Mileposts -
OS Operator
Stations

Distance From Davenport Jct	Stations	Distance to next Station	Stn Code	Crew Change Point
	SUMNER SUBDIVISION			
45.0	Sumner Station - West Terminus OS	5.0	SM	Yes
	WEST CLINTON SUBDIVISION			
40.0	Santa Fe Station	4.0	SF	Yes
36.0	Clinton Diamond	2.0	CD	
	SOLVANG SUBDIVISION			
34.0	Solvang Tunnel East Portal	4.0	STE	
30.0	Solvang Tunnel West Portal	5.0	STW	
	CLINTON SUBDIVISION			
25.0	Clinton Ind Spur	2.0	CI	
23.0	Clinton Station OS	2.0	CS	Yes
21.0	West Clinton Tower	1.0	WC	Yes
	PORTAGE SUBDIVISION			
20.0	Portage Engine House	4.0	PE	
16.0	Portage Jct East Turnout	2.0	EPJ	Yes
14.0	Portage Jct Diamond	2.0	PD	
	FULLERTON SUBDIVISION			
12.0	West Division Diamond	1.0	WD	
11.0	Fullerton Connector OS	1.0	FC	Yes
	TOLEDO SUBDIVISION			
10.0	Toledo Ind Spur R4	5.5	TIS	
4.5	Toledo Jct OS	0.5	TJ	
	WEST PORTAGE SUBDIVISION			
4.0	Portage Jct	1.0	PJ	Yes
3.0	Portage Diamond	1.0	PD	
	DAVENPORT SUBDIVISION			
2.0	Davenport Diamond OS	2.0	DD	
0.0	Davenport Junction - East Terminus	0.0	EP	Yes